

According to recent acknowledgement from Samsung, a fingerprint sensor issue may allow any fingerprint to unlock a fingerprint-protected device has been found to affect certain Samsung devices. Affected models include **Galaxy Note 10/10+/10+ 5G, S10/S10+/S10e/S10 light/S10 5G/Tab S6.**

Customer using Samsung's fingerprint sensors are changed to utilize pattern or passwords until a fix has been issued to prevent unauthorized login on SC Mobile, or access 'Scan and Pay' or 'SC Keyboard Banking' services.